



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

57417

## Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	2/12/2010
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S1180A		

<b>Serial Number</b>	92843
<b>Model Number</b>	SBE 09Plus

## Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

## Problems Found:

1. The 6-pin Auxiliary connector was found to have corrosion damage.

## Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW six pin bulkhead connector(s).
3. Performed internal inspection and O-ring replacement.
4. Performed hydrostatic pressure test.
5. Calibrated the pressure sensor.
6. Performed complete system check and full diagnostic evaluation.

## Special Notes:

--