Service	Report		RMA Number	596	24			
Customer Info	ormation:							
Company	Oregon State Unive	ersity			Date	8/11/2010		
Contact	Dave O Gorman							
PO Number	S1180A							
Serial Number Model Number			Ī					
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.								
Problems Fou	ınd:							
Services Performed:								
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 								
Special Notes	»: 							

Service	Report		RMA Number	596	24				
Customer Info	ormation:								
Company	Oregon State Unive	ersity			Date	8/11/2010			
Contact	Dave O Gorman								
PO Number	S1180A								
Serial Number									
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.									
Problems Fou	ınd:								
Services Perf	Services Performed:								
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 									
Special Notes	»: 								

Service	_						
	Report		RMA N	Number	596	524	
Customer Inf	ormation:						
Company	Oregon State University	/				Date	8/11/2010
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number							
	uested: pair Instrumentation. utine Calibration Service.						
Problems For	und:						
Services Perf	ormed:						
	nitial diagnostic evaluation of the contraction of		ıre senso	r.			
Special Notes	3 :						

Service							
3011100	Report		RMA Number	5962	24		
Customer Info	ormation:						
oustonier init							
Company	Oregon State Unive	rsity			Date	8/11/2010	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number	032767						
Model Number	SBE 03S						
Services Req	uested:						
1. Evaluate/Rep	oair Instrumentation.						
2. Perform Rou	tine Calibration Serv	ice.					
Problems Fou	ınd:						
Services Perf	ormed:						
1. Performed in	itial diagnostic evalu	ation.					
2. Performed "Post Cruise" calibration of the temperature sensor.							
Special Notes)!						

Service	_					
Service	Report		RMA Number	5	9624	
	Пероп					
Customer Infe	ormation:					
Company	Oregon State University	1			Date	8/11/2010
Contact	Dave O Gorman					
PO Number	S1180A					
Serial Number	03P2327					
Model Number	er SBE 03Plus					
Services Req	uested:					
1. Evaluate/Re	pair Instrumentation.					
2. Perform Rou	itine Calibration Service.					
Problems For	und:					
Services Perf	ormed:					
	nitial diagnostic evaluatio	n.				
	Post Cruise" calibration of					
	nternal inspection and O- ydrostatic pressure test.	ring replaceme	nt.			
	Final" calibration of the to	emperature ser	sor.			
Special Notes						
Special Notes).					

Camina							
Service	Ronart		RMA N	umber	596	24	
	Report		"		*1		
Customer Info	ormation:						
Company	Oregon State Univer	sity				Date	8/11/2010
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number	03P2329						
Model Number	SBE 03Plus						
Services Req	uested:						
Evaluate/Re Perform Rou	pair Instrumentation. Itine Calibration Servi	20					
2. 1 011011111100	time Gambration Gervi						
Problems For	und:						
Services Perf	ormed:						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 							
Special Notes	3 :						

Service	Report		RMA Number	5962	24		
Customer Info	ormation:						
Company	Oregon State Universi	ty			Date	8/11/2010	
Contact PO Number	Dave O Gorman S1180A						
Serial Number							
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.							
Problems Fou	ınd:						
Services Perf	ormed:						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes	::						

Service	_						
<u> </u>	Poport		RMA Number	596	24		
	Report		•	1			
Customer Info	ormation:						
Company	Oregon State Universit	/			Date	8/11/2010	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Numbe	041896						
Model Number	SBE 04C						
Services Req	uested:						
Evaluate/Rep Perform Rou	oair Instrumentation. tine Calibration Service.						
Problems Fou	ınd:						
	eached end of life. ivity cell was found to re	quire cleaning	and re-platinizatio	n.			
Services Perf	ormed:						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. Cleaned and replatinized the conductivity cell. Performed "Final" calibration of the conductivity sensor. Installed NEW zinc anode ring. 							
Special Notes:							

Service	Report		RMA Number	5962	24		
	перин						
Customer Infe	ormation:						
Company	Oregon State Unive	rsity			Date	8/11/2010	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number							
Model Number	er SBE 04M						
Services Req							
Evaluate/Re Perform Rou	pair Instrumentation. Itine Calibration Serv	ice.					
Problems For	und:						
Services Perf	ormed:						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes	S:						