



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63973

Customer Information:

Company	Oregon State University	Date	6/17/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	09P5745-0250
Model Number	SBE 09Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The 3-pin bulkhead connector located at JB5 was found to have slight corrosion damage.
2. Both end caps were found to have corrosion damage. Replacement of both end caps is recommended.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Calibrated the pressure sensor.
3. Performed internal inspection and O-ring replacement.
4. Performed hydrostatic pressure test.
5. Performed complete system check and full diagnostic evaluation.

Special Notes:

Customer did not want the end caps replaced at this time.



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	63973
-------------------	-------

Customer Information:

Company	Oregon State University	Date	6/17/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	3215736-0194
Model Number	SBE 32

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

--

Services Performed:

<ol style="list-style-type: none">1. Performed initial diagnostic evaluation.2. Performed internal inspection and O-ring replacement.3. Performed hydrostatic pressure test.4. Replaced anode(s).5. Performed complete system check and full diagnostic evaluation.

Special Notes:

--