## SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	Report		RMA Nu	ımber	6623	5	
Customer Information:							
Company	Oregon State Universit	у				Date	11/9/2011
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number	09P6012-0256						
Model Number   SBE 09Plus							
Services Requested:							
1. Evaluate/Repair Instrumentation.							
2. Perform Rou	tine Calibration Service						
Problems Found:							
<ol> <li>Water damage on AP counter board.</li> <li>The connector located at JB4 was found to have an intermitten connection after we quoted the customer.</li> </ol>							
2. The services resident at the real of the services are the services and the services are							
Services Performed:							
Performed initial diagnostic evaluation.							
2. Installed NEW AP counter board.							
<ul><li>3. Installed NEW three pin bulkhead connector(s). *</li><li>4. Performed internal inspection and O-ring replacement.</li></ul>							
5. Performed hydrostatic pressure test.							
<ul><li>6. Calibrated the pressure sensor.</li><li>7. Performed complete system check and full diagnostic evaluation.</li></ul>							
Special Notes	<b>S:</b>						
* This was repla	ced at no additional cha	arge.					