SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service							
CCITICC	Report		RMA Number	7181	13		
Customer Infe	ormation:						
Company	Oregon State Unive	rsity			Date	12/5/2012	
Contact	Dave O Gorman						
PO Number	TBD						
Serial Number	03P2327						
Model Number SBE 03Plus							
Services Requested:							
1. Evaluate/Repair Instrumentation.							
2. Perform Rou	itine Calibration Ser	rice.					
Problems Found:							
r robienis i dunu.							
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 							
2. 1 onormod 1 oot oraide damoration of the temperature sensor.							
Special Notes:							
-							
		on of the tempera	ture sensor.				

SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service							
COLLIGO	Report		RMA Number	7181	13		
Customer Info	ormation:						
Company	Oregon State Unive	ersity			Date	12/5/2012	
Contact	Dave O Gorman						
PO Number	TBD						
Serial Number	03P2329						
Model Number SBE 03Plus							
Services Requested:							
1. Evaluate/Rep	pair Instrumentation						
2. Perform Rou	itine Calibration Ser	rice.					
Problems Found:							
Services Performed:							
Performed initial diagnostic evaluation.							
Performed "Post Cruise" calibration of the temperature sensor.							
Special Notes	· .						
opcolar Hotes	7.						

SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	Report		RMA Number	718	13		
Customer Info	ormation:						
Company	Oregon State Unive	ersity			Date	12/5/2012	
Contact	Dave O Gorman						
PO Number	TBD						
Serial Number 041568 Model Number SBE 04-01/0							
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.							
Problems Found:							
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes:							