Service								
	Report		RMA Num	ber	771	74		
	Пероп							
Customer Information:								
Company	Oregon State University					Date	3/20/2014	
Contact	Johna Winters							
PO Number	TBD							
Serial Numbe	4556968-0360							
Model Numb	SRF 45							
Services Req	uested:							
<ol> <li>Evaluate/Repair Instrumentation.</li> <li>Perform Routine Calibration Service.</li> </ol>								
Problems Found:								
Services Performed:								
1. Performed initial diagnostic evaluation.								
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.								
3. Performed internal inspection and O-ring replacement.								
4. Performed complete system check and full diagnostic evaluation.								
Special Notes:								

Service									
	Report		RMA Numb	er	7717	4			
Customer Information:									
Company	Oregon State University					Date	3/20/2014		
Contact	Johna Winters								
PO Number	TBD								
Serial Number   4556968-0361									
Services Requested:  1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.									
Problems Found:									
The conductivity cell was found to require cleaning and re-platinization.									
Services Perfe	ormed:								
1. Performed in	itial diagnostic evaluation.								
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.									
3. Cleaned and replatinized the conductivity cell.									
4. Performed "Final" calibration of the temperature & conductivity sensors.									
5. Performed internal inspection and O-ring replacement.									
6. Performed complete system check and full diagnostic evaluation.									
Special Notes:									

Service								
	Report		RMA Numbe	r	7717	74		
	Пороге							
Customer Information:								
Company	Oregon State University					Date	3/20/2014	
Contact	Johna Winters							
PO Number	TBD							
Serial Numbe	480046							
Model Numb	SRF 48							
Services Req	uested:							
Evaluate/Repair Instrumentation.     Perform Routine Calibration Service.								
Problems Found:								
Services Performed:								
1. Performed in	nitial diagnostic evaluation	۱.						
Performed "Post Cruise" calibration of the temperature sensor.								
3. Installed NEW 9 Volt lithium battery.								
4. Performed complete system check and full diagnostic evaluation.								
Special Notes:								

Service								
	Ī	RMA Number	771	74				
Report	· ·							
Customer Information:								
Company Oregon State Univer	sity			Date	3/20/2014			
Contact Johna Winters								
PO Number TBD								
Serial Number 480047								
Model Number   SRF 48								
Services Requested:								
Evaluate/Repair Instrumentation.								
2. Perform Routine Calibration Servi	ce.							
Problems Found:								
Problems Found:								
Services Performed:								
Performed initial diagnostic evaluation.								
Performed "Post Cruise" calibration of the temperature sensor.								
· ·								
3. Installed NEW 9 Volt lithium battery.								
4. Performed complete system check and full diagnostic evaluation.								
Special Notes:								