

Service	10111					
<u> </u>	Report		RMA Number	7732	27	
	Перен					
Customer Information:						
Company	Oregon State Unive	rsity			Date	3/7/2014
Contact	Johna Winters					
PO Number	TBD					
Model Number   040497   SBE 04-01/0						
	-					
Services Requ	uested:					
Evaluate/Repair Instrumentation.     Partition and O. Birat Banks are at the second of the seco						
<ol> <li>Perform Internal Inspection and O-Ring Replacement.</li> <li>Perform Routine Calibration Service.</li> </ol>						
Problems Found:						
FIODICIIIS FOUIIU.						
Services Performed:						
Performed initial diagnostic evaluation.						
Performed internal inspection and O-ring replacement.						
Performed hydrostatic pressure test.						
4. Performed "Final" calibration of the conductivity sensor.						
Special Notes:						

Page 1 of 4 Friday, March 07, 2014



Service	¬   =						
	Report	RMA Number	7732	27			
Customer Information:							
Company	Oregon State University			Date	3/7/2014		
Contact	Johna Winters						
PO Number	TBD						
Serial Number 041568							
Model Number	SRF 04-01/0						
Services Req	uested:						
<ol> <li>Evaluate/Repair Instrumentation.</li> <li>Perform Internal Inspection and O-Ring Replacement.</li> <li>Perform Routine Calibration Service.</li> </ol>							
Problems Found:							
Services Perf	ormed:						
1. Performed initial diagnostic evaluation.							
2. Performed "Post Cruise" calibration of the conductivity sensor.							
3. Performed internal inspection and O-ring replacement.							
4. Performed hydrostatic pressure test.							
5. Performed "Final" calibration of the conductivity sensor.							
Special Notes	:						

Page 2 of 4 Friday, March 07, 2014



Service						
	Report	MA Number 7732	27			
Customer Information:						
Company	Oregon State University		<b>Date</b> 3/7/2014			
Contact	Johna Winters					
PO Number	TBD					
Serial Number   3856968-0605						
Services Requ	uested:					
<ol> <li>Evaluate/Repair Instrumentation.</li> <li>Perform Internal Inspection and O-Ring Replacement.</li> <li>Perform Routine Calibration Service.</li> </ol>						
Problems Found:						
Services Performed:						
Performed initial diagnostic evaluation.						
2. Performed "Post Cruise" calibration of the temperature sensor.						
3. Performed internal inspection and O-ring replacement.						
4. Performed hydrostatic pressure test.						
5. Performed "Final" calibration of the temperature sensor.						
6. Performed complete system check and full diagnostic evaluation.						
Special Notes:						

Page 3 of 4 Friday, March 07, 2014



Service							
	Report		RMA Number	7732	7		
Customer Information:							
Company	Oregon State University				Date	3/7/2014	
Contact	Johna Winters						
PO Number	TBD						
Serial Number	3856968-0607						
Model Number	SRF 38						
Services Requested:							
<ol> <li>Evaluate/Repair Instrumentation.</li> <li>Perform Internal Inspection and O-Ring Replacement.</li> <li>Perform Routine Calibration Service.</li> </ol>							
Problems Found:							
Services Perf	ormed:						
1. Performed in	itial diagnostic evaluation.						
2. Performed "Post Cruise" calibration of the temperature sensor.							
3. Performed internal inspection and O-ring replacement.							
4. Performed hydrostatic pressure test.							
5. Performed "Final" calibration of the temperature sensor.							
Performed complete system check and full diagnostic evaluation.							
Special Notes:							

Page 4 of 4 Friday, March 07, 2014