

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	Report		RMA Number	7860)4	
Customer Inf	ormation:					
Company	Oregon State Unive	rsity			Date	7/24/2014
Contact PO Number	Johna Winters TBD					
Serial Number						

Thursday, July 24, 2014 Page 1 of 3



Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service		RMA Number 7860				
	Report	NIVIA INUITIDEI	, 			
Customer Info	ormation:					
Company	Oregon State University		Date 7/24/2014			
Contact	Johna Winters					
PO Number	TBD					
Services Requested:						
 Evaluate/Repair Instrumentation. Replace standard impulse connector(s) with NEW wet-pluggable connector(s). Perform Routine Calibration Service. 						
Problems Found:						
Services Performed:						
	itial diagnostic evaluation.					
2. Installed NE\	N two pin wet-pluggable bulkhead conn	ector(s), female.				
3. Installed NE\	N three pin wet-pluggable bulkhead con	nector(s).				
4. Installed NE\	N six pin wet-pluggable bulkhead conne	ctor(s).				
5. CONN, MCDC-3-F, Female Dummy for MCIL/BH-3-MP						
6. Installed NEW 9Plus top end cap.						
7. Installed NEW bottom end cap. *						
8. Installed NEW 6800 meter housing.						
Performed internal inspection and O-ring replacement.						
10. Performed I	nydrostatic pressure test.					
11. Calibrated t	he pressure sensor.					
12. Replaced anode(s).						
13. Performed complete system check and full diagnostic evaluation.						

Thursday, July 24, 2014 Page 2 of 3

Special Notes:



Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	Report	RMA Number	78604	
Customer Info	ormation:			
Company	Oregon State University		Date	7/24/2014
Contact	Johna Winters			
PO Number	TBD			

Page 3 of 3 Thursday, July 24, 2014