



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

78903

Customer Information:

Company	Oregon State University	Date	5/8/2014
Contact	Johna Winters		
PO Number	S1624A		

Serial Number	051335
Model Number	SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW two pin wet-pluggable bulkhead connector(s).
3. Performed internal inspection and O-ring and thrust washer replacements.
4. Performed hydrostatic pressure test.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

78903

Customer Information:

Company	Oregon State University	Date	5/8/2014
----------------	-------------------------	-------------	----------

Contact	Johna Winters
----------------	---------------

PO Number	S1624A
------------------	--------

Serial Number	051336
----------------------	--------

Model Number	SBE 05T
---------------------	---------

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW two pin wet-pluggable bulkhead connector(s).
3. Performed internal inspection and O-ring and thrust washer replacements.
4. Performed hydrostatic pressure test.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

78903

Customer Information:

Company	Oregon State University	Date	5/8/2014
Contact	Johna Winters		
PO Number	S1624A		

Serial Number	051770
Model Number	SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW two pin wet-pluggable bulkhead connector(s).
3. Performed internal inspection and O-ring and thrust washer replacements.
4. Performed hydrostatic pressure test.

Special Notes:

--