



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79487

Customer Information:

Company Oregon State University **Date** 7/21/2014

Contact Johna Winters

PO Number S1624A

Serial Number 030997

Model Number SBE 03-01/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79487

Customer Information:

Company Oregon State University **Date** 7/21/2014

Contact Johna Winters

PO Number S1624A

Serial Number 031008

Model Number SBE 03-01/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	79487
-------------------	--------------

Customer Information:

Company	Oregon State University	Date	7/21/2014
Contact	Johna Winters		
PO Number	S1624A		

Serial Number	031364
Model Number	SBE 03-01/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79487

Customer Information:

Company Oregon State University **Date** 7/21/2014

Contact Johna Winters

PO Number S1624A

Serial Number 031366

Model Number SBE 03-01/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79487

Customer Information:

Company Oregon State University **Date** 7/21/2014

Contact Johna Winters

PO Number S1624A

Serial Number 031384

Model Number SBE 03-02/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

Special Notes:

--