



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

79499

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	7/21/2014
----------------	-------------------------	-------------	-----------

<b>Contact</b>	Johna Winters
----------------	---------------

<b>PO Number</b>	S1624A
------------------	--------

<b>Serial Number</b>	040497
----------------------	--------

<b>Model Number</b>	SBE 04-01/0
---------------------	-------------

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

79499

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	7/21/2014
<b>Contact</b>	Johna Winters		
<b>PO Number</b>	S1624A		

<b>Serial Number</b>	040670
<b>Model Number</b>	SBE 0401/O

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

79499

### Customer Information:

**Company** Oregon State University **Date** 7/21/2014

**Contact** Johna Winters

**PO Number** S1624A

**Serial Number** 041018

**Model Number** SBE 04-01/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

79499

### Customer Information:

**Company** Oregon State University **Date** 7/21/2014

**Contact** Johna Winters

**PO Number** S1624A

**Serial Number** 041070

**Model Number** SBE 04-01/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

79499

### Customer Information:

**Company** Oregon State University **Date** 7/21/2014

**Contact** Johna Winters

**PO Number** S1624A

**Serial Number** 041568

**Model Number** SBE 04-01/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

### Special Notes:

--