



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

84705

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	6/24/2015
----------------	-------------------------	-------------	-----------

<b>Contact</b>	Johna Winters
----------------	---------------

<b>PO Number</b>	TBD
------------------	-----

<b>Serial Number</b>	031364
<b>Model Number</b>	SBE 03-01/F

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

84705

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	6/24/2015
<b>Contact</b>	Johna Winters		
<b>PO Number</b>	TBD		

<b>Serial Number</b>	031366
<b>Model Number</b>	SBE 03-01/F

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

84705

### Customer Information:

**Company** Oregon State University **Date** 6/24/2015

**Contact** Johna Winters

**PO Number** TBD

<b>Serial Number</b>	031384
<b>Model Number</b>	SBE 03-02/F

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--