Comments:

## Temperature Calibration Report

Customer:	Oregon State Ur	niversity		
Job Number:	59625	Date of R	eport:	5/19/2010
Model Number:	SBE 03-01/S	Serial Nu	mber:	030854
the calibration iden calibration is not po An 'as received' cal must choose wheth during deployment. allows a small corre	atifies a problem, then overformed if the sensor libration certificate is per the 'as received' call in SEASOFT enter to the for drift between pair apply only to subse	•	r work is comp sustomer reques t sensor frequer etter represents ram SEACON	leted. The 'as received' st. ncy to temperature. Users the sensor condition . The coefficient 'offset'
<b>Date:</b> 5/18/2010		Drift since last cal	+0.003	Degrees Celsius/year
Comments:				
'CALIBRATION	AFTER REPAIR'		Performed	✓ Not Performed
Date:		Drift since Last cal	l:	Degrees Celsius/year