Comments:

Temperature Calibration Report

Customer:	Oregon State U	niversity		
Job Number:	68054	Date of Repor	rt:	3/14/2012
Model Number	SBE 38	Serial Numbe	er:	3856968-0604
If the calibration is calibration is not p An 'as received' ca must choose wheth during deployment	dentifies a problem, the verformed if the sensor libration certificate is p ver the 'as received' call t. In SEASOFT enter t rations (consult the SE	ted 'as received', without adjustments, allon a second calibration is performed after wis damaged or non-functional, or by custon rovided, listing coefficients to convert sensibration or the previous calibration better the chosen coefficients. The coefficient of ASOFT manual). Calibration coefficients	vork is con mer reques sor frequen represents ffset' allow	npleted. The 'as received' it. ncy to temperature. Users the sensor condition s a small correction for
Date: 3/14/2012	2	Drift since last cal:	-0.0004	Degrees Celsius/year
Comments:				
'CALIBRATION	1 FORD DED 1 751	□ Parf	ormed	✓ Not Performed