



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	48012
-------------------	-------

Customer Information:

Company	Oregon State University	Date	9/14/2007
Contact	Dave O Gorman		
PO Number	No Charge		

Serial Number	041021
Model Number	SBE 04-01/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. Conductivity cell is broken on the endcap side. New cell needed.
2. Housing threads are stripped out. New housing needed.
3. Endcap has broken off bolts stuck in it. New endcap needed.

Services Performed:

1. Performed initial diagnostic evaluation.

Special Notes:

Customer has decided not to repair this sensor at this time.
This sensor has been returned "AS-IS".