



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	51842
-------------------	-------

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
----------------	-------------------------	-------------	-----------

<b>Contact</b>	Dave O Gorman
----------------	---------------

<b>PO Number</b>	S0953A
------------------	--------

<b>Serial Number</b>	031367
<b>Model Number</b>	SBE 03-02/F

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	51842
-------------------	-------

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S0953A		

<b>Serial Number</b>	032767
<b>Model Number</b>	SBE 03S

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	51842
-------------------	-------

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S0953A		

<b>Serial Number</b>	03P2329
<b>Model Number</b>	SBE 03Plus

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Backfilled sensor with ARGON gas.
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

51842

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S0953A		

<b>Serial Number</b>	041538
<b>Model Number</b>	SBE 04-02/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

51842

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S0953A		

<b>Serial Number</b>	041568
<b>Model Number</b>	SBE 04-01/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	51842
-------------------	-------

### Customer Information:

<b>Company</b>	Oregon State University	<b>Date</b>	9/19/2008
<b>Contact</b>	Dave O Gorman		
<b>PO Number</b>	S0953A		

<b>Serial Number</b>	041896
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--