Service						
	Report		RMA Number	5334	1	
Customer Inf	ormation:					
Company	Oregon State Univers	ty			Date	2/17/2009
Contact PO Number	Dave O Gorman S0953A					
Serial Number						
Services Req	uested:					
<ol> <li>Evaluate/Re</li> <li>Perform Rou</li> </ol>	pair Instrumentation. Itine Calibration Service	Э.				
Problems For	und:					
Services Perf	ormed:					
	nitial diagnostic evaluat Post Cruise" calibration		ure sensor.			
Special Notes	<b>3</b> :					

Service		` _		5004				
	Report		RMA Number	5334	,1			
Customer Info	ormation:							
Company	Oregon State Univers	ity			Date	2/17/2009		
Contact PO Number	Dave O Gorman S0953A							
Serial Number			_					
Services Req	uested:							
Evaluate/Rep     Perform Rou	pair Instrumentation. Itine Calibration Servic	e.						
Problems For	und:							
Services Perf	ormed:							
Performed initial diagnostic evaluation.     Performed "Post Cruise" calibration of the temperature sensor.								
Special Notes	S:							

Comica						
Service	Popert		RMA Number	5334	41	
	Report		•	·-		
<b>Customer Info</b>	ormation:					
Company	Oregon State Universit	у			Date	2/17/2009
Contact	Dave O Gorman					
PO Number	S0953A					
Serial Number	031008					
Model Number	er SBE 03-01/F					
Services Req	uested:					
	pair Instrumentation.					
z. Penomi Rou	itine Calibration Service	•				
Problems Fou	ınd:					
Services Perf	ormod:					
	nitial diagnostic evaluati	\n				
	Post Cruise" calibration		ture sensor.			
3. Backfilled se	nsor with ARGON gas.	·				
4. Performed "F	Final" calibration of the	emperature se	nsor.			
Special Notes	3:					

Comica						
Service			RMA Number	5334	41	
	Report			<u> </u>		
Customer Info	ormation:					
Company	Oregon State Univers	sity			Date	2/17/2009
Contact	Dave O Gorman					
PO Number	S0953A		_			
Serial Number	o31364					
Model Number						
Services Req	uested:					
1. Evaluate/Re	pair Instrumentation.					
2. Perform Rou	itine Calibration Service	e.				
Problems For	und:					
Services Perf	formed:					
	nitial diagnostic evalua					
	Post Cruise" calibratio ensor with ARGON gas		ture sensor.			
	Final" calibration of the		ensor.			
Special Notes	s:					

Comica						
Service	Popert		RMA Number	5334	11	
	Report			**************************************		
Customer Inf	ormation:					
Company	Oregon State Universit	у			Date	2/17/2009
Contact	Dave O Gorman					
PO Number	S0953A					
Serial Number	031366					
Model Number	SBE 03-01/F					
Services Req	uested:					
	pair Instrumentation. Itine Calibration Service					
Z. T GHOIIII NOC	nine Cambration Service	•				
Problems For	und:					
Services Perf	ormed:					
1. Performed in	nitial diagnostic evaluation	on.				
2. Performed "I	Post Cruise" calibration		ture sensor.			
	ensor with ARGON gas. Final" calibration of the t	emperature se	ensor.			
		j				
Special Notes	S:					

Service			RMA Number	5334	11	
	Report		Number	3004		
Customer Info	ormation:					
Company	Oregon State Univers	ity			Date	2/17/2009
Contact PO Number	Dave O Gorman S0953A					
Serial Number						
Services Req	uested:					
Evaluate/Re     Perform Rou	pair Instrumentation. tine Calibration Servic	е.				
Problems For	und:					
Services Perf	ormed:					
	nitial diagnostic evaluat Post Cruise" calibration		rity sensor.			
Special Notes	<b>S:</b>					

Service			RMA Number	5334	1	
	Report		NIMA Number	5554	''	
Customer Inf	ormation:					
Company	Oregon State Univers	ity			Date	2/17/2009
Contact PO Number	Dave O Gorman S0953A					
Serial Number						
Services Req	uested:					
<ol> <li>Evaluate/Re</li> <li>Perform Rou</li> </ol>	pair Instrumentation. Itine Calibration Servic	9.				
Problems For	und:					
Services Perf	ormed:					
	nitial diagnostic evaluat Post Cruise" calibration		rity sensor.			
Special Notes	<b>S</b> :					

Service	Danaut		RMA Number	5334	11	
	Report		•	4 +		
Customer Info	ormation:					
Company	Oregon State Univer	sity			Date	2/17/2009
Contact	Dave O Gorman					
PO Number	S0953A					
Serial Number						
Model Number	SBE 04-01/0					
Services Req	uested:					
Evaluate/Rep     Perform Rou	pair Instrumentation. tine Calibration Servi	ce.				
Problems Fou	ınd:					
Services Perf	ormed:					
	nitial diagnostic evalua		vity appar			
z. renomied i	Post Cruise" calibration	on the conductiv	ily Selisur.			
Special Notes	<b>:</b> :					

Service						
Service	Panart		RMA Number	5334	<b>41</b>	
	Report		•	•		
<b>Customer Info</b>	ormation:					
Company	Oregon State Unive	ersity			Date	2/17/2009
Contact	Dave O Gorman					
PO Number	S0953A					
Serial Number	041898					
Model Number	SBE 04C		I			
Services Req	uested:					
Evaluate/Rep     Perform Rou	pair Instrumentation itine Calibration Serv	vice.				
Problems Fou	ınd:					
Services Perf	ormed:					
	nitial diagnostic evalu Post Cruise" calibrat		ctivity sensor.			
Special Notes	S:					

	_						
Service	Poport		RMA Numl	ber	53341		
	Report			•			
<b>Customer Inf</b>	ormation:						
Company	Oregon State Universi	ty				Date	2/17/2009
Contact	Dave O Gorman						
PO Number	S0953A						
Serial Number	430387						
Model Number	er SBE 43						
Services Req	uested:						
	pair Instrumentation. itine Calibration Service	).					
Problems For	und:						
Services Perf	ormed:						
2. Performed "I	nitial diagnostic evaluati Post Cruise" calibration ull diagnostic evaluation	of the oxygen se	ensor.				
Special Notes	s:						
3. Performed fu	ull diagnostic evaluation		ensor.				