

Service									
Service			RMA Number	645	10				
	Report		1	<u></u>					
Customer Info	Customer Information:								
Company	Oregon State Univers	ty			Date	6/27/2011			
Contact	Dave O Gorman		7						
	S1180A		_						
PO Number	51160A								
Serial Numbe	r 041029								
Model Number									
Services Requ									
1. Evaluate/Rep	pair Instrumentation. tine Calibration Servic								
2. Perform Rou	tine Calibration Servic).							
Problems Fou	ınd:								
Services Perf	ormed:								
1. Performed in	itial diagnostic evaluat	on.							
2. Performed "Post Cruise" calibration of the conductivity sensor.									
3. Cleaned and replatinized the conductivity cell.									
4. Performed internal inspection and O-ring replacement.									
5. Performed hydrostatic pressure test.6. Performed "Final" calibration of the conductivity sensor.									
S. I SHOIIIIGG I	ar canoration of the	co. Iddolivity Sci							
Chariel Natas									
Special Notes									

Page 1 of 5 Monday, June 27, 2011



Service	Report		RMA Number	6451	10			
Customer Info	ormation:							
Company	Oregon State Universit	у			Date	6/27/2011		
Contact	Dave O Gorman							
PO Number	S1180A							
Serial Number Model Number								
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.								
Problems Found:								
Services Performed:								
O. Performed "Post Cruise" calibration of the conductivity sensor. 1. Performed initial diagnostic evaluation.								
Special Notes:								

Page 2 of 5 Monday, June 27, 2011



Service Customer Info	Report		RMA Nu	ımber	6451	0	
Company	Oregon State Unive	rsity				Date	6/27/2011
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number	041568						
Model Number	SBE 04-01/0						
Problems Fou	pair Instrumentation. tine Calibration Serv und:	ce.					
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes:							
		-					

Page 3 of 5 Monday, June 27, 2011



Service	Report		RMA Number	645	i10		
Customer Info	ormation:						
Company	Oregon State Unive	ersity			Date	6/27/2011	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number							
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service.							
Problems Found:							
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes:							

Monday, June 27, 2011 Page 4 of 5



Service						
<u> </u>	Panart		RMA Number	645	10	
	Report			*		
Customer Inf	ormation:					
Company	Oregon State Universi	у			Date	6/27/2011
Contact	Dave O Gorman					
PO Number	S1180A					
Serial Number	431232					
Model Numb	er SBE 43					
Services Req	uested:					
	pair Instrumentation. Itine Calibration Service	-				
Problems For	und:					
Services Perf	ormed:					
2. Performed "l	nitial diagnostic evaluati Post Cruise" calibration Ill diagnostic evaluation	of the oxygen s	ensor.			
Special Notes	s:					

Page 5 of 5 Monday, June 27, 2011