

| Comico | | | | | | |
|------------------|---|------------------|-------------|---------|------|----------|
| Service | | | RMA Number | 651 | 123 | |
| | Report | | , | | | |
| Customer Info | ormation: | | | | | |
| Company | Oregon State University | / | | | Date | 8/5/2011 |
| Contact | Dave O Gorman | | | | | |
| PO Number | S1180A | | | | | |
| Serial Number | 031369 | | | | | |
| Model Number | er SBE 03-02/F | | | | | |
| Services Req | uested: | | | | | |
| | pair Instrumentation. Itine Calibration Service. | | | | | |
| Z. Fellollii hou | illile Calibration Service. | | | | | |
| Problems For | und: | | | | | |
| 1. The anode w | vas found to be near end | of life. | | | | |
| | | | | | | |
| Services Perf | ormed: | | | | | |
| | nitial diagnostic evaluatio | | | | | |
| | Post Cruise" calibration o W zinc anode ring. | of the temperati | ure sensor. | | | |
| | | | | | | |
| Special Notes | s: | | | | | |
| | | | | | | |
| | | | | | | |

Friday, August 05, 2011 Page 1 of 8



| Service | Report | | RMA Number | 651 | 23 | |
|--|---|--------|---------------|-----|------|----------|
| Customer Info | ormation: | | | | | |
| Company | Oregon State Unive | ersity | | | Date | 8/5/2011 |
| Contact | Dave O Gorman | | | | | |
| PO Number | S1180A | | | | | |
| Serial Number Model Number | | | | | | |
| Services Required 1. Evaluate/Rep 2. Perform Rou | uested: pair Instrumentation tine Calibration Ser | vice. | | | | |
| Problems Fou | ınd: | | | | | |
| | | | | | | |
| Services Perf | ormed: | | | | | |
| | itial diagnostic evali Post Cruise" calibrat | | ature sensor. | | | |
| Special Notes | »: | | | | | |
| | | | | | | |

Friday, August 05, 2011 Page 2 of 8



| Comico | _ | | | | | |
|----------------|--|----------|-------------|--------------|------|----------|
| Service | Danari | | RMA Number | 651 | 123 | |
| | Report | | • | , * <u> </u> | | |
| Customer Info | ormation: | | | | | |
| Company | Oregon State University | | | | Date | 8/5/2011 |
| Contact | Dave O Gorman | | | | | |
| PO Number | S1180A | | | | | |
| Serial Number | o31384 | | | | | |
| Model Number | | | | | | |
| Services Req | uested: | | | | | |
| 1. Evaluate/Re | pair Instrumentation. | | | | | |
| 2. Perform Rou | itine Calibration Service. | | | | | |
| Problems Fou | und: | | | | | |
| 1. The anode w | vas found to be near end | of life. | | | | |
| | | | | | | |
| Services Perf | iormodi | | | | | |
| | | | | | | |
| | nitial diagnostic evaluation Post Cruise" calibration o | | ıre sensor. | | | |
| | W zinc anode ring. | · | | | | |
| On a sial Nata | | | | | | |
| Special Notes | 5: | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Friday, August 05, 2011 Page 3 of 8



| Service | | | | | | | | |
|---|--|--|------------|------|------|----------|--|--|
| Service | - Romant | | RMA Number | 6512 | 23 | | | |
| | Report | | • | | | | | |
| Customer Info | ormation: | | | | | | | |
| Company | Oregon State Univer | sity | | | Date | 8/5/2011 | | |
| Contact | Dave O Gorman | | | | | | | |
| PO Number | S1180A | | | | | | | |
| Serial Numbe | 032633 | | | | | | | |
| Model Number | SBE 03 | | | | | | | |
| Services Requ | uested: | | | | | | | |
| | oair Instrumentation. tine Calibration Servi | e. | | | | | | |
| Problems Found: | | | | | | | | |
| Services Perf | | | | | | | | |
| Performed "F Backfilled se Performed in Performed hy | itial diagnostic evalua Post Cruise" calibrationsor with ARGON gasternal inspection and ydrostatic pressure tesinal" calibration of the | n of the temperat c. O-ring replacement. | ent. | | | | | |
| Special Notes |): | | | | | | | |
| | | | | | | | | |

Friday, August 05, 2011 Page 4 of 8



| Report 65123 Customer Information: | |
|--|------|
| Customer Information: | |
| | |
| Company Oregon State University Date 8/5/2 | 011 |
| Company Oregon State University Date 8/5/2 | .011 |
| Contact Dave O Gorman | |
| PO Number S1180A | |
| Serial Number 03P2329 | |
| Model Number SBE 03Plus | |
| Services Requested: | |
| Evaluate/Repair Instrumentation. Perform Routine Calibration Service. | |
| 2. Perform Routine Calibration Service. | |
| Problems Found: | |
| | |
| | |
| | |
| Services Performed: | |
| Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. | |
| | |
| Special Notes: | |
| | |
| | |

Friday, August 05, 2011 Page 5 of 8



| Service | Report | RI | //A Number | 65123 | |
|---|--|-------------------------------------|------------|-------|----------|
| Customer Info | ormation: | | | | |
| Company | Oregon State Unive | sity | | Date | 8/5/2011 |
| Contact | Dave O Gorman | | | | |
| PO Number | S1180A | | | | |
| Serial Numbe | 041896 | | | | |
| Model Number | SBE 04C | | | | |
| 1. Evaluate/Rep 2. Perform Rou Problems Fou | pair Instrumentation. tine Calibration Serv | ce. | | | |
| | itial diagnostic evalu | ation. on of the conductivity se | ensor. | | |
| Special Notes | : : | | | | |

Friday, August 05, 2011 Page 6 of 8



| Service | Report | | RMA Number | 651 | 23 | |
|--|---|--------|----------------|-----|------|----------|
| Customer Info | ormation: | | | | | |
| Company | Oregon State Unive | ersity | | | Date | 8/5/2011 |
| Contact | Dave O Gorman | | | | | |
| PO Number | S1180A | | | | | |
| Serial Number | | | | | | |
| Services Required 1. Evaluate/Rep 2. Perform Rou | uested: pair Instrumentation tine Calibration Ser | vice. | | | | |
| Problems Fou | ınd: | | | | | |
| | | | | | | |
| Services Perf | ormed: | | | | | |
| | itial diagnostic eval Post Cruise" calibrat | | tivity sensor. | | | |
| Special Notes | : | | | | | |
| | | | | | | |

Friday, August 05, 2011 Page 7 of 8



| Service | | | | | | | | | |
|---------------------|--|-------|---------|------------|--------|------|------|---------|---|
| | Report | | | RMA | Number | 6512 | 3 | | |
| | Пероп | | | | | | | | |
| Customer Inf | ormation: | | | | | | | | |
| Company | Oregon State Univ | rsity | | | | | Date | 8/5/201 | 1 |
| Contact | Dave O Gorman | | | | | | | | |
| PO Number | S1180A | | | | | | | | |
| Serial Number | 3856968-060 | | | | | | | | |
| Model Numb | er SBE 38 | | | | | | | | |
| Services Req | uested: | | | | | | | | |
| 1. Evaluate/Re | pair Instrumentatior | : | | | | | | | |
| z. Penonii not | nine Calibration Ser | ice. | | | | | | | |
| Problems For | und: | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Services Perf | formed: | | | | | | | | |
| | nitial diagnostic eval Post Cruise" calibra | | omporat | uro oono | or | | | | |
| | omplete system che | | | | | | | | |
| | | | | | | | | | |
| Special Notes | s: | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

Friday, August 05, 2011 Page 8 of 8