

Service	Report		RMA Number	699	958	
Customer Info	ormation:					
Company	Oregon State Universi	У			Date	8/3/2012
o o	Dave O Gorman S1180A					
Serial Numbe	r 031384					
Model Number	SBE 03-02/F					
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service. Problems Found:						
Services Perfe						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. Backfilled sensor with ARGON gas. Performed internal inspection and O-ring replacement. Performed hydrostatic pressure test. Performed "Final" calibration of the temperature sensor. 						
Special Notes	:					

Friday, August 03, 2012 Page 1 of 5



Service	Report		RMA Number	6995	58		
Customer Info	ormation:						
Company	Oregon State Unive	ersity			Date	8/3/2012	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number							
Services Req 1. Evaluate/Rep 2. Perform Rou	uested: pair Instrumentation tine Calibration Sen	vice.					
Problems Fou	Problems Found:						
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 							
Special Notes):						

Friday, August 03, 2012 Page 2 of 5



Service	Report		RMA Number	699	58		
Customer Info	ormation:						
Company	Oregon State Unive	ersity			Date	8/3/2012	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number							
Services Required 1. Evaluate/Rep 2. Perform Rou	uested: pair Instrumentation tine Calibration Ser	vice.					
Problems Found:							
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Special Notes	»:						

Friday, August 03, 2012 Page 3 of 5



Service			RMA Number	6995	58		
	Report		<u> </u>	.			
Customer Info	ormation:						
Company	Oregon State Unive	rsity			Date	8/3/2012	
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Number	o41896						
Model Number	SBE 04C						
Services Req	uested:						
1. Evaluate/Rep	pair Instrumentation tine Calibration Serv	ioo					
z. Feliolili hou	une Canbration Serv	ice.					
Problems Fou	ınd:						
Sarvicas Darf	ormed:						
Services Performed: 1. Performed initial diagnostic evaluation.							
Performed "Post Cruise" calibration of the conductivity sensor.							
_							
Special Notes) .						

Friday, August 03, 2012 Page 4 of 5



Service								
Service	Report		RMA Number	699	58			
	Пероп							
Customer Infe	ormation:							
Company	Oregon State Univers	ty			Date	8/3/2012		
Contact	Dave O Gorman							
PO Number	S1180A							
Serial Number	er 042356							
Model Number	er SBE 04M							
Services Req	uested:							
1. Evaluate/Re	pair Instrumentation.							
2. Perform Rou	itine Calibration Servic).						
Problems For	und:							
Services Perf	formed:							
	Performed initial diagnostic evaluation.							
2. Performed "Post Cruise" calibration of the conductivity sensor.								
 Performed internal inspection and O-ring replacement. Performed hydrostatic pressure test. 								
5. Performed "Final" calibration of the conductivity sensor.								
Special Notes	· .							
Opcolar Hotes	J.							

Friday, August 03, 2012 Page 5 of 5