Service	¬ =					
			RMA Number	7525	52	
	Report		4			
Customer Info	ormation:					
Company	Oregon State University				Date	8/1/2013
Contact	Dave O Gorman]			
PO Number	S1472A		-			
Serial Number	er 030997					
Model Number						
Services Req	uested:					
1. Evaluate/Rep	pair Instrumentation. tine Calibration Service.					
Problems Fou	ınd:					
Services Perf	ormed:					
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. Backfilled sensor with ARGON gas. * Performed internal inspection and O-ring replacement. * Performed hydrostatic pressure test. * Performed "Final" calibration of the temperature sensor. 						
Special Notes	S :					
* These service:	s were performed at no c	harge.				

Service		_					
<u> </u>	Poport		RMA Number	752	52		
	Report		•	I M			
Customer Info	ormation:						
Company	Oregon State Unive	sity			Date	8/1/2013	
Contact	Dave O Gorman						
PO Number	S1472A						
Serial Number	er 031008						
Model Number	SBE 03-01/F						
Services Req	uested:						
1. Evaluate/Re	pair Instrumentation. Itine Calibration Serv	20					
Z. Fellollii hou	illile Calibration Serv						
Problems Fou	und:						
Services Perf	ormed:						
Performed initial diagnostic evaluation.							
2. Performed "F	Post Cruise" calibration	n of the temperat	ure sensor.				
Special Notes	: :						
	·						

Comitos							
Service RMA Number 75252							
Report							
Customer Information:							
Company Oregon State University Date 8/	/2013						
Contact Dave O Gorman							
PO Number S1472A							
Serial Number 031364							
Model Number SBE 03-01/F							
Services Requested:							
1. Evaluate/Repair Instrumentation.							
Perform Routine Calibration Service.							
Problems Found:							
Services Performed:							
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature sensor. 							
2. Tenorified Tost Ordise Calibration of the temperature sensor.							
Special Notes:							

Service	<u> </u>						
<u> </u>	Bonort		RMA Number	r 752	252		
	Report		*	*1			
Customer Inf	ormation:						
Company	Oregon State Univers	sity			Date	8/1/2013	
Contact	Dave O Gorman				I		
PO Number	S1472A						
Serial Number	er 031366						
Model Number	er SBE 03-01/F						
Services Req	uested:						
Evaluate/Re Perform Re	pair Instrumentation. Itine Calibration Servic	20					
Z. Pellollii hou	illie Calibration Servic	.e.					
Problems For	und:						
Services Perf	formed:						
Performed initial diagnostic evaluation.							
2. Performed "I	Post Cruise" calibratio	n of the temper	ature sensor.				
Special Notes	s:						
	-						

Service	Report		RMA Number	75	5252		
Customer Info	ormation:						
Company	Oregon State University				Date	8/1/2013	
Jointagt .	Dave O Gorman S1472A						
Serial Numbe							
Model Number	SBE 03-02/F						
Services Requested: 1. Evaluate/Repair Instrumentation. 2. Perform Routine Calibration Service. Problems Found:							
 Performed "F Backfilled sei Performed in Performed hy 	itial diagnostic evaluation on the control of the test of the control of the test of the control of the test of the control of	f the temperati ring replaceme *	ent. *				
Special Notes * These services	: s were performed at no c	harge.					

Service							
<u> </u>	Papart		RMA Number	7525	2		
	Report		•	•			
Customer Info	ormation:						
Company	Oregon State Universi	у			Date	8/1/2013	
Contact	Dave O Gorman						
PO Number	S1472A						
Serial Number	er 040670						
Model Number	SBE 0401/O						
Services Req	uested:						
1. Evaluate/Rep	pair Instrumentation. Itine Calibration Service						
z. Peliolili hou	une Cambration Service	•					
Problems Fou	und:						
Services Perf	ormed:						
	nitial diagnostic evaluati		vity concer				
	Post Cruise" calibration sternal inspection and C						
Performed internal inspection and O-ring replacement. * Performed hydrostatic pressure test. *							
Performed "F	Final" calibration of the	conductivity ser	isor. *				
Special Notes	:						
•	s were performed at no	charge					
111000 301 1100.	e iisio ponoimou at no	J. 141 90.					

Service							
<u> </u>	Panart		RMA Number	7525	2		
	Report		•	•			
Customer Info	ormation:						
Company	Oregon State Universi	:y			Date	8/1/2013	
Contact	Dave O Gorman						
PO Number	S1472A						
Serial Numbe	er 041018						
Model Number	SBE 04-01/0						
Services Req	uested:						
Evaluate/Rep Perform Pour	pair Instrumentation. Itine Calibration Service						
Z. Fellollii hou	une Cambration Service						
Problems Fou	und:						
Services Perf	ormed:						
	nitial diagnostic evaluati						
	Post Cruise" calibration						
Performed internal inspection and O-ring replacement. * Performed hydrostatic pressure test. *							
	-inal" calibration of the		isor.				
Special Notes	···						
•		-1					
i nese service	s were performed at no	cnarge.					

Service	_					
Cervice	Report		RMA Number	7525	52	
Customer Info	ormation:					
Company	Oregon State University				Date	8/1/2013
Contact	Dave O Gorman					
PO Number	S1472A					
Serial Numbe	r 041030					
Model Number	SBE 04-02/0					
Services Requ	uested:					
Evaluate/Rep Perform Rour	pair Instrumentation. tine Calibration Service.					
Z. T enomition	une danbration dervice.					
Problems Fou	ınd:					
Services Perfe	ormed:					
Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. Performed internal inspection and O-ring replacement. Performed hydrostatic pressure test. Performed "Final" calibration of the conductivity sensor.						
Special Notes						
* These services	s were performed at no c	harge.				

Service	_					
	Report		RMA Number	7525	52	
Customer Info	ormation:					
Company	Oregon State University				Date	8/1/2013
Contact	Dave O Gorman					
PO Number	S1472A					
Serial Numbe	r 041070					
Model Number	SBE 04-01/0					
Services Requ	uested:					
Evaluate/Rep Perform Rou	pair Instrumentation. tine Calibration Service.					
Z. T enomition	tine Galibration Gervice.					
Problems Fou	ınd:					
Services Perf	ormed:					
1. Performed initial diagnostic evaluation. 2. Performed "Post Cruise" calibration of the conductivity sensor. 3. Performed internal inspection and O-ring replacement. 4. Performed hydrostatic pressure test. 5. Performed "Final" calibration of the conductivity sensor.						
Special Notes	:					
* These services	s were performed at no c	harge.				

Service							
Service	Donout		RMA Number	752	52		
	Report		+				
Customer Info	ormation:						
Company	Oregon State Unive	rsity			Date	8/1/2013	
Contact	Dave O Gorman						
PO Number	S1472A						
Serial Numbe	r 041898						
Model Number	SBE 04C						
Services Requ	uested:						
Evaluate/Rep Perform Rou	oair Instrumentation. tine Calibration Serv	ice					
2. 1 011011111100							
Problems Fou	ınd:						
Services Perf	ormed:						
 Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the conductivity sensor. 							
Z. Fellollileu F	osi Gruise Calibrati	on or the conductiv	nty senson.				
Special Notes) :						