## SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	Report		RMA Number	8257	7	
<b>Customer Inf</b>	ormation:					
Company	Oregon State Univers	ity			Date	2/23/2015
Contact PO Number	Johna Winters S1472A					
Serial Number 430463						
Model Numb	er SBE 43					

## SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service							
Service	Report	RMA Number	8257	77			
Customer Info							
Company	Oregon State University			Date	2/23/2015		
Contact	Johna Winters						
PO Number	S1472A						
Services Requested:							
<ol> <li>Evaluate/Repair Instrumentation.</li> <li>Perform Routine Calibration Service.</li> </ol>							
Problems Fou	ınd:						
Air was under the membrane. Corroded getter.							
Services Performed:							
Performed initial diagnostic evaluation. *							
2. Performed "Post Cruise" calibration of the oxygen sensor. *							
3. Replaced the SBE 43 Anode sub assembly. *							
4. Replaced the SBE 43 Getter sub assembly. *							
5. Replaced the lid and membrane assembly (0.5 mil). *							
6. Replaced the electrolyte with new fluid. *							
7. Replaced the SBE 43 electronic board set. *							
8. Installed NEW board mounted battery. *							
9. Performed internal inspection and O-ring replacement. *							
10. Performed hydrostatic pressure test. *							
11. Performed "Final" calibration of the oxygen sensor. *							
12. Performed full diagnostic evaluation. *							
Special Notes	:						
* All services we	ere performed at no charge.						

## SBE SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service						
	Report		RMA Number	825	77	
	110,0010					
Customer Information:						
Company	Oregon State University				Date	2/23/2015
Contact	Johna Winters					
PO Number	S1472A					
Serial Number	431232					
Model Number   SBE 43						
Services Requested:						
Evaluate/Repair Instrumentation.     Perform Routine Calibration Service.						
Problems Found:						
Services Performed:						
1. Performed initial diagnostic evaluation.						
2. Performed "Post Cruise" calibration of the oxygen sensor.						
3. Performed full diagnostic evaluation.						
Special Notes:						