

SEA-BIRD ELECTRONICS, INC. 1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Oregon State Ur	niversity			
Job Number:	55396	Dat	e of Repo	ort:	7/31/2009
Model Number:	SBE 03Slow	Ser	ial Numb	er:	032548
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request. An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition					
during deployment. In SEASOFT enter the chosen coefficients using the program SEACON. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data. 'AS RECEIVED CALIBRATION' Performed Not Performed					
Date: 7/31/2009	<u> </u>	Drift since la	Г	-0.0008	
Comments:					
'CALIBRATION .	AFTER REPAIR'		□ Pei	rformed	✓ Not Performed
Date:	1	Drift since I			Degrees Celsius/year
Comments:					