The O-rings were replaced.

Temperature Calibration Report

Customer:	Oregon State Un	iversity	
Job Number:	77327	Date of Report:	2/25/2014
Model Number	SBE 38	Serial Number:	3856968-0607
If the calibration id calibration is not po An 'as received' cal must choose wheth during deployment.	lentifies a problem, then erformed if the sensor is libration certificate is presented to the sensor the sensor the sensor the sensor the sensor (consult the SEA CALIBRATION'	ted 'as received', without adjustments, allowin n a second calibration is performed after work is damaged or non-functional, or by customer rovided, listing coefficients to convert sensor fi- bration or the previous calibration better repr ne chosen coefficients. The coefficient 'offset' ASOFT manual). Calibration coefficients obta	is completed. The 'as received' request. requency to temperature. Users esents the sensor condition allows a small correction for ained after a repair apply only to
Date: 2/14/2014		Drift since last cal: +0	Degrees Cersius/year
Comments:			
'FINAL CALIBRA	ATION'	✓ Perform	ned
Date: 2/25/2014	.]	Drift since 21 Nov 12 +	0.00011 Degrees Celsius/year
Comments:			