Oregon State University

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Oregon State University	ersity		
Job Number:	82618	Da	te of Report:	1/22/2015
Model Number	SBE 38	Sei	rial Number:	3856968-0607
the calibration iden	tifies a problem, then a se	l 'as received', without adj econd calibration is perfor lamaged or non-functiona	med after work is com	
must choose whethe during deployment.	er the 'as received' calibra In SEASOFT enter the ations (consult the SEAS	ition or the previous calib chosen coefficients. The	ration better represent coefficient 'offset' allov	ws a small correction for after a repair apply only to
Date:		Drift since 1		✓ Not Performed Degrees Celsius/year
Comments:	_	21110 311100 1		
'FINAL CALIBRA			✓ Performed	□ Not Performed
Date: 1/21/2015]	Drift since?	25 Feb 14 -0.00	Degrees Celsius/year
Comments:	s upgraded at check-	in		