

Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0361
CALIBRATION DATE: 27-Sep-11

SBE 45 TEMPERATURE CALIBRATION DATA
ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS

a0 = 3.271698e-005
a1 = 2.767240e-004
a2 = -2.694914e-006
a3 = 1.572124e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	689018.4	1.0000	0.0000
4.5000	587644.5	4.5000	-0.0000
15.0000	371828.7	15.0000	0.0000
18.5000	321227.5	18.4999	-0.0001
24.0000	256794.1	24.0001	0.0001
29.0000	210797.7	28.9999	-0.0001
32.5001	184210.1	32.5001	0.0000

Temperature ITS-90 = $1 / \{a_0 + a_1[\ln(n)] + a_2[\ln^2(n)] + a_3[\ln^3(n)]\} - 273.15$ (°C)

Residual = instrument temperature - bath temperature

