

VAISALA

Handled by
Juha Vanhatalo

Forwarding agent
UNITED PARCEL SERVICE FINLAN

SERVICE REPORT

Date
22/12/09
Seller's reference
9627490

Buyer's reference
SM#9476

Page 1

Consignee
Vaisala Inc., Boston Office
10-D Gill Street
Woburn MA 01801
United States

Invoicing address(if not consignee)
Vaisala Inc.
Boulder Operations
194 South Taylor Ave.
Louisville CO 80027
United States

Pos	Description	Serial number	Quantity
1	PTU300 Pressure, Humidity and Temperature Transmitter ((18/12/2009 15:18 vvu)) --DESCRIPTION OF NONCONFORMANCE GIVEN BY THE CUSTOMER-- Calibration --CAUSE OF NONCONFORMANCE-- Unit has broken Humicap sensor and needs repair. --CORRECTIVE ACTION-- Humicap sensor and filter replaced. Operation tested, adjustments made and unit was calibrated. Calibration certificate number S02789 (before adjustment) H37-09500001 (analog output) -- S02898 (after adjustment) issued.	C2610002	1