



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

| |
|----------------|
| Service |
| Report |

RMA Number

47892

Customer Information:

| | | | |
|------------------|-------------------------|-------------|-----------|
| Company | Oregon State University | Date | 9/12/2007 |
| Contact | Dave O Gorman | | |
| PO Number | S0953A | | |

| | |
|----------------------|------------|
| Serial Number | 032490 |
| Model Number | SBE 03Slow |

Services Requested:

| |
|---|
| 1. Perform Routine Calibration Service. |
|---|

Problems Found:

| |
|--|
| |
|--|

Services Performed:

| |
|---|
| 1. Performed initial diagnostic evaluation. |
| 2. Performed "Post Cruise" calibration of the temperature sensor. |

Special Notes:

| |
|--|
| |
|--|



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

| |
|----------------|
| Service |
| Report |

| | |
|-------------------|-------|
| RMA Number | 47892 |
|-------------------|-------|

Customer Information:

| | | | |
|----------------|-------------------------|-------------|-----------|
| Company | Oregon State University | Date | 9/12/2007 |
|----------------|-------------------------|-------------|-----------|

| | |
|----------------|---------------|
| Contact | Dave O Gorman |
|----------------|---------------|

| | |
|------------------|--------|
| PO Number | S0953A |
|------------------|--------|

| | |
|----------------------|--------|
| Serial Number | 430463 |
| Model Number | SBE 43 |

Services Requested:

| |
|---|
| 1. Perform Routine Calibration Service. |
|---|

Problems Found:

| |
|--|
| |
|--|

Services Performed:

| |
|---|
| 1. Performed initial diagnostic evaluation. 2. Performed "Post Cruise" calibration of the oxygen sensor. 3. Performed full diagnostic evaluation. |
|---|

Special Notes:

| |
|--|
| |
|--|