

### Customer Information:

Company	Oregon State University	Date	5/29/2009
Contact	Dave O Gorman		
PO Number	S0953A		
•			

Serial Number	431232
Model Number	SBE 43

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Performed full diagnostic evaluation.

# Special Notes: