



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	55397
-------------------	-------

Customer Information:

Company	Oregon State University	Date	8/25/2009
----------------	-------------------------	-------------	-----------

Contact	Dave O Gorman
----------------	---------------

PO Number	S1180A
------------------	--------

Serial Number	031367
Model Number	SBE 03-02/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

55397

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	03P2327
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

55397

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	03P2329
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	55397
-------------------	-------

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	041030
Model Number	SBE 04-02/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	55397
-------------------	-------

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	041553
Model Number	SBE 04-01/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

55397

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	041898
Model Number	SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Cleaned and replatinized the conductivity cell.
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	55397
-------------------	-------

Customer Information:

Company	Oregon State University	Date	8/25/2009
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	042356
Model Number	SBE 04M

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--