

L	Report	RMA Number	603	03	
Customer In	formation:				
Company	Oregon State University			Date	8/9/2010
Contact	Dave O Gorman				
PO Number	S1180A				
Sorial Numb	er 430387				

Model Number | SBE 43

Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Performed full diagnostic evaluation.

Special Notes: