



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	64841
-------------------	-------

Customer Information:

Company	Oregon State University	Date	7/11/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	041553
Model Number	SBE 04-01/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The 3-pin bulkhead connector was found to have corrosion damage.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.
3. Installed NEW three pin bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	64841
-------------------	-------

Customer Information:

Company	Oregon State University	Date	7/11/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	430463
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--