



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

65303

Customer Information:

Company	Oregon State University	Date	8/19/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	030573
Model Number	SBE 03-01/S

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The anode was found to be near end of life.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Installed NEW zinc anode ring.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

65303

Customer Information:

Company	Oregon State University	Date	8/19/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	030854
Model Number	SBE 03-01/S

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	65303
-------------------	-------

Customer Information:

Company	Oregon State University	Date	8/19/2011
Contact	Dave O Gorman		
PO Number	S1180A		

Serial Number	032767
Model Number	SBE 03S

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--