SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service							
Cervice	Report		RMA Nur	mber	659 ⁻	15	
	нероп						
Customer Information:							
Company	Oregon State University	,				Date	10/3/2011
Contact	Dave O Gorman						
PO Number	S1180A						
Serial Numbe	4556968-0361						
Model Number SBE 45							
Services Requested:							
 Evaluate/Repair Instrumentation. Perform Routine Calibration Service. 							
Z. Pellollii hou	une Cambration Service.						
Problems Found:							
Services Performed:							
Performed initial diagnostic evaluation. Performed "Post Cruise" calibration of the temperature % conductivity conserved.							
 Performed "Post Cruise" calibration of the temperature & conductivity sensors. Performed internal inspection and O-ring replacement. 							
4. Performed hydrostatic pressure test.							
5. Performed co	omplete system check a	nd full diagnos	tic evaluation	l .			
Special Notes:							