## SEA-BIRD ELECTRONICS, INC. 13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service							
Service	Report		RMA N	lumber	718	12	
	Пероп						
Customer Information:							
Company	Oregon State University					Date	12/17/2012
Contact	David O Gorman						
PO Number	TBD						
Serial Number	er 4556968-0360						
Model Number   SBE 45							
Services Requested:							
Evaluate/Repair Instrumentation.     Perform Routine Calibration Service.							
2. Perioriii Rou	lline Calibration Service.						
Problems Found:							
		-					
Services Performed:							
<ol> <li>Performed initial diagnostic evaluation.</li> <li>Performed "Post Cruise" calibration of the temperature &amp; conductivity sensors.</li> </ol>							
<ol> <li>Performed internal inspection and O-ring replacement.</li> <li>Performed hydrostatic pressure test.</li> </ol>							
5. Performed c	omplete system check an	d full diagnost	ic evaluati	on.			
Special Notes	<b>3:</b>						
-poo.a. 110100		1					