



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

74196

Customer Information:

Company Oregon State University **Date** 7/24/2013

Contact Dave O Gorman

PO Number S1472A

Serial Number 430387

Model Number SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

1. The membrane was badly wrinkled.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Replaced the lid and membrane assembly (0.5 mil).
3. Replaced the electrolyte with new fluid.
4. Performed hydrostatic pressure test.
5. Performed "Final" calibration of the oxygen sensor.
6. Performed full diagnostic evaluation.

Special Notes:

--