



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79336

Customer Information:

Company	Oregon State University	Date	4/29/2014
Contact	Johna Winters		
PO Number	TBD		

Serial Number	430387
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Replace standard impulse connector(s) with NEW wet-pluggable connector(s).
3. Perform Routine Calibration Service.

Problems Found:

1. Customer requested wet-pluggable connector upgrade.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Installed NEW four pin wet-pluggable bulkhead connector(s).
4. Performed internal inspection and O-ring replacement.
5. Performed hydrostatic pressure test.
6. Performed "Final" calibration of the oxygen sensor.
7. Performed full diagnostic evaluation.

Special Notes:

--