



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

82722

Customer Information:

Company	Oregon State University	Date	2/23/2015
----------------	-------------------------	-------------	-----------

Contact	Johna Winters
----------------	---------------

PO Number	S1472A
------------------	--------

Serial Number	041538
----------------------	--------

Model Number	SBE 04-02/0
---------------------	-------------

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

82722

Customer Information:

Company	Oregon State University	Date	2/23/2015
Contact	Johna Winters		
PO Number	S1472A		

Serial Number	041553
Model Number	SBE 04-01/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

82722

Customer Information:

Company Oregon State University **Date** 2/23/2015

Contact Johna Winters

PO Number S1472A

Serial Number 041568

Model Number SBE 04-01/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

82722

Customer Information:

Company Oregon State University **Date** 2/23/2015

Contact Johna Winters

PO Number S1472A

Serial Number 041896

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

82722

Customer Information:

Company Oregon State University **Date** 2/23/2015

Contact Johna Winters

PO Number S1472A

Serial Number 042356

Model Number SBE 04M

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--