



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

|                |
|----------------|
| <b>Service</b> |
| <b>Report</b>  |

**RMA Number**

84704

### Customer Information:

**Company** Oregon State University **Date** 7/6/2015

**Contact** Johna Winters

**PO Number** TBD

**Serial Number** 041018

**Model Number** SBE 04-01/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

|  |
|--|
|  |
|--|

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

|  |
|--|
|  |
|--|



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

|                |
|----------------|
| <b>Service</b> |
| <b>Report</b>  |

**RMA Number**

84704

### Customer Information:

**Company** Oregon State University **Date** 7/6/2015

**Contact** Johna Winters

**PO Number** TBD

**Serial Number** 041029

**Model Number** SBE 04

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

|  |
|--|
|  |
|--|

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

|  |
|--|
|  |
|--|



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

|                |
|----------------|
| <b>Service</b> |
| <b>Report</b>  |

**RMA Number**

84704

### Customer Information:

**Company** Oregon State University **Date** 7/6/2015

**Contact** Johna Winters

**PO Number** TBD

**Serial Number** 041030

**Model Number** SBE 04-02/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

|  |
|--|
|  |
|--|

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

|  |
|--|
|  |
|--|



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

|                |
|----------------|
| <b>Service</b> |
| <b>Report</b>  |

**RMA Number**

84704

### Customer Information:

|                  |                         |             |          |
|------------------|-------------------------|-------------|----------|
| <b>Company</b>   | Oregon State University | <b>Date</b> | 7/6/2015 |
| <b>Contact</b>   | Johna Winters           |             |          |
| <b>PO Number</b> | TBD                     |             |          |

|                      |             |
|----------------------|-------------|
| <b>Serial Number</b> | 041070      |
| <b>Model Number</b>  | SBE 04-01/0 |

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

1. The conductivity sensor was found to have failed.
2. The conductivity cell was found to have failed.
3. New connector needed due to the flood.
4. A new board set is needed p/n 80994T due to the flooding of this unit.

### Services Performed:

1. Performed initial diagnostic evaluation. \*

### Special Notes:

\* Customer has declined repairs at this time.